



EXHIBIT J



TREE SURVEY LEGEND



1
PROPOSED TREE IMPACTS & SITE SLOPES
SCALE: 1" = 200'



TREE TYPE	SYMBOL	EXISTING	FULL TREE REMOVAL			TREE FELLING - NO STUMPING			TOTAL	
			SLOPE <15%	SLOPE >15%	SUBTOTAL	SLOPE <15%	SLOPE >15%	SUBTOTAL		
NON-INVASIVE DEAD	○	138	53	36	89	1	3	4	93	
NON-INVASIVE POOR CONDITION	●	67	19	18	37	0	3	3	40	
NON-INVASIVE CRITICAL CONDITION	○○	102	24	20	44	2	0	2	46	
NON-INVASIVE FAIR CONDITION	★	1,288	263	414	677	18	26	44	721	
NON-INVASIVE GOOD CONDITION	○○○	553	107	186	293	2	15	17	310	
INVASIVE TREES	☒	1,447	263	298	561	23	28	51	612	
		TOTAL	3,595	729	972	1,701	46	75	121	1,822



It is a violation of New York Education Law Article 145 Sec.7209, for any person, unless acting under the direction of a licensed architect, professional engineer, or land surveyor, to alter any survey or map if an item, feature, or seal of an architect, engineer, or land surveyor is altered; the altering architect, engineer, or land surveyor shall affix to the item their seal and notation "altered by" followed by their signature and date of such alteration, and a specific description of the alteration.

YSG SOLAR
79 MADISON AVE
NEW YORK, NY 10016



BRIARCLIFF SOLAR ARRAY
345 SCARBOROUGH RD
BRIARCLIFF MANOR, NY 10510

0 100.0002 200.0004 400.0008
1:2400.03480001 Feet

-- -- --
NO: DATE: DESCRIPTION:
REVISIONS
PROJECT NUMBER:
DRAWN BY: JCT
REVIEWED BY: JCT
ISSUED FOR: REVIEW
DATE: FEBRUARY 2023
DRAWING NAME:
DRAWING NUMBER:

TREE IMPACTS